

Penyusunan Laporan Pelaksanaan Renovasi Rumah Tidak Layak Huni

KABUPATEN PONOROGO - 2025

No	Data Pemilik	Dok. 0 %	Dok. 50 %	Dok. 100 %
137	Nama : Jainem Alamat : RT/RW 01/01 Dkh. Nglingi Desa/Kel : Ngebel Latitude : -7.79460 Longitude : 111.64140			
138	Nama : Ahmat Kosim Alamat : RT/RW 03/02 Dkh. Keleng Desa/Kel : Ngebel Latitude : -7.78676 Longitude : 111.63537			
139	Nama : Yatir Alamat : RT/RW 03/02 Dkh. Keleng Desa/Kel : Ngebel Latitude : -7.78716 Longitude : 111.62111			
140	Nama : M. Supriyono Alamat : RT/RW 02/02 Dkh. Sahang Desa/Kel : Sahang Latitude : -7.80709 Longitude : 111.61316			
141	Nama : Purwadi Alamat : RT/RW 01/02 Dkh. Ngrogung Desa/Kel : Ngrogung Latitude : -7.80050 Longitude : 111.61684			
142	Nama : Suwarti Alamat : RT/RW 02/01 Dkh. Pucuk Desa/Kel : Wagir Lor Latitude : -7.81396 Longitude : 111.62962			

Penyusunan Laporan Pelaksanaan Renovasi Rumah Tidak Layak Huni

KABUPATEN PONOROGO - 2025

No	Data Pemilik	Dok. 0 %	Dok. 50 %	Dok. 100 %
143	Nama : Sakem Alamat : RT/RW 01/01 Dkh. Sahang Desa/Kel : Sahang Latitude : -7.80644 Longitude : 111.62075			