

**Penyusunan Laporan Pelaksanaan Renovasi Rumah Tidak Layak Huni
KABUPATEN BANYUWANGI - 2025**

Kecamatan : Tegaldlimo

No.	Nama	No.KTP/NIK	Desa	Alamat	Pekerjaan Renovasi RTLH				
					Lantai (m2)	Dinding (m2)	Jendela (unit)	Pintu (unit)	Pondasi(m)
1	2	3	4	5	6	7	8	9	10
1	SUPIN	3510045001550005	Tegaldlimo	Dsn Sumberdadi RT.030 RW.005	24,00	20,00	2	1	20,00
2	ANDI	3510042908980002	Wringinpitu	Dsn.Ringin Anom RT.003 RW.001	24,00	20,00	2	1	20,00
3	NGATEMIN	3510040812520003	Kedungasri	Ds.Persen RT.016/RW.003	24,00	20,00	2	1	20,00
4	TUKINI	3510044301450000	Purwoasri	Dsn.Tegalsari Lor RT.013 RW.003	24,00	20,00	2	1	20,00
Jumlah :			4						